



## Smoke and Dye-Water Observation Summary

### Western Run Pilot Project - Baltimore Maryland

#### FIELD SKETCH

Dye Test 153

Page 1 of 2  
Smoke Set No. 22  
Setup No. 1  
153

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/22/04	Start Time: 0830
Crew: T2	Street Location: Greenspring Ave		
US MH: 1520789	DS MH: 1520795	Number of Segments: 7	Test Length: 1454'
Plugged US: <input checked="" type="checkbox"/> N	Plugged DS: <input checked="" type="checkbox"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="checkbox"/> Dry Moderate Wet
Plugs Removed? <input checked="" type="checkbox"/> N	Recorder: Bob Blank	Comments:	

**FIELD SKETCH** (show manholes and ID numbers; blower placement; source addresses; sandbag locations, etc.)

MH 05112-021

Dye was put in a Downspout drain

Dye was seen in this San. MH

MH 05112-020

MH 05112-022

Defect B4

This was the only sketch/data available for Unique Id 153. This was a positive test. Dye was seen in MH 05112-020

**CREW COMMENTS:**

B4 is the smoking drain pipe from the downspout.

Last Revised 9/16/2004

Leader Form

Sketch No: 153

#### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\153.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.